

HISTORIC AMERICAN BUILDING SURVEY
INDEX TO PHOTOGRAPHS

HABS
ID
32-RICHFIELD
1A-

JAMES H. LANE RANCH, BARN
One mile south of Richfield and Highway 26
Richfield
Lincoln County
Idaho

HABS No. ID-113-A

F.Brent Smith, Photographer August 10, 1995

- ID-113-A-1 VIEW OF JAMES H. LANE BARN (HEREAFTER LANE BARN) FROM L.D.S. CHURCH GROUNDS ON IDAHO HIGHWAY 26, APPROXIMATELY 1/4 MILE EAST OF THE MAIN INTERSECTION OF RICHFIELD, IDAHO. CAMERA IS POINTING SOUTH.
- ID-113-A-2 VIEW OF LANE BARN WITH RELATIONSHIP TO LITTLE WOOD RIVER. THE MAIN INTERSECTION OF RICHFIELD IS LOCATED THROUGH THE TREES IN THE RIGHT CENTER OF IMAGE. CAMERA IS POINTING NORTH/NORTHWEST.
- ID-113-A-3 VIEW OF LANE BARN WITH LITTLE WOOD RIVER AND IDAHO IRRIGATION COMPANY PUMP HOUSE ON RIGHT. CAMERA POINTED NORTHEAST.
- ID-113-A-4 OBLIQUE VIEW OF WEST AND SOUTH SIDES. CAMERA POINTED EAST/NORTHEAST.
- ID-113-A-5 OBLIQUE VIEW OF EAST AND NORTH SIDES. CAMERA POINTED WEST/SOUTHWEST.
- ID-113-A-6 VIEW OF EAST ELEVATION. CAMERA POINTED WEST.
- ID-113-A-7 VIEW OF SOUTH ELEVATION. CAMERA POINTED NORTH.
- ID-113-A-8 VIEW OF WEST ELEVATION. CAMERA POINTED EAST.
- ID-113-A-9 VIEW OF NORTH ELEVATION. CAMERA POINTED SOUTH.
- ID-113-A-10 DETAIL VIEW OF EAST ELEVATION WITH UPPER DOOR/SIDING, AND CONCRETE DOOR LINTEL. CAMERA POINTED WEST.
- ID-113-A-11 DETAIL VIEW OF WEST ELEVATION/CONCRETE POST AND LINTEL REINFORCEMENT. CAMERA POINTED EAST.
- ID-113-A-12 DETAIL OF WINDOWS ON SOUTHEAST CORNER OF BUILDING. CAMERA POINT SOUTH/SOUTHWEST.

JAMES H. LANE RANCH, BARN
HABS. No. ID-113-A (Page 2)
INDEX TO PHOTOGRAPHS

- ID-113-A-13 DETAIL OF SOUTH SIDE WINDOW AND ROCK WORK WITH BEADED MORTAR LINE. CAMERA POINTED NORTHWEST.
- ID-113-A-14 DETAIL OF ROOF TRUSS STRUCTURE AND HAY HOOK CABLE AND PULLEY SYSTEM LOCATED ON WEST END OF BARN. CAMERA POINTED EAST.
- ID-113-A-15 INTERIOR VIEW FROM SOUTHWEST CORNER (INTERIOR ROOM #17, AND FEED WINDOW #16 ARE VISIBLE). CAMERA POINTED EAST/ NORTHEAST.
- ID-113-A-16 DETAIL OF FEED WINDOW IN NORTH WALL OF BARN. CAMERA POINTING NORTH.
- ID-113-A-17 VIEW OF INTERIOR MILKING ROOM WITH ROCK WALL CONSTRUCTION. CAMERA POINTED EAST.
- ID-113-A-18 DETAIL OF DOOR CONSTRUCTION. (DOOR LEANED AGAINST SOUTH INTERIOR WALL). CAMERA POINTING SOUTH.